# Kerikeri Cruising Club (KCC) Marina Committee Minutes

# Meeting of the Marina Committee Tuesday 11 July 2017 at Kerikeri Cruising Marina Office & Boatshed, 346 Opito Bay Road, Kerikeri.

# The meeting commenced at 6.30pm

#### 1 Attending

P Harris (Chair), P Pederson, P Williams, P Stocker, K Staff

M MacDiarmid, P McLea, (attending)

### 2 Apologies

J Murdoch, L Ayr

Resolution	That the apology from J Murdoch be accepted.	
	Proposed P Harris/Seconded P Williams:	Carried

# 3 Confirmation of minutes of previous meeting

Resolution	That the minutes of the meeting 13 June 2017 be accepted.	
	Proposed P Pederson/Seconded P Stocker: Carried	

# 4 Health & Safety

No incidents this month

#### 5 Maintenance

B pier twisted fingers	Replacement whalers/bearers are being replaced installed,
Haul out Winch	Brake coil, seal & brake pads being replaced – haul outs not
	possible until these repairs are completed.
Sanivac	Being refurbished
Marina Condition Audit	Completed -
Pile Guides	Stainless steel or galvanised – P McLea pricing stainless steel & galvanised options & summarise life span of galvanised v condition of ss.
E Pier	E30 flitch plate & through bolts, \$66,500 + GST – Total Marine Tauranga contractor is a possibility – P McLea to pursue 2 quotes for the job Engineer to attend when E30 flitch plate is being replaced

Resolution	That the Breakwater Refurbishment job is defined as replacement of flitch plates &
	whalers at E30, all through bolts on the breakwater (except those running through

110717min.doc 1

the inspections hatches), & marina piles as identified in the marina condition audit.
Get a 2 <sup>nd</sup> quote for that job.
Proposed P Harris/Seconded K Staff: Carried

Annual Marina Condition	Highlights
Audit	12 piles need replacing
	7 standard pile guides need replacing
	1 wide pile guide need replacing
	12 pile guides can be repaired with an L plate.
	Stainless composite pile guides being priced up.
	E pier 3 whalers are showing signs of rot
	A & B gangways – rust needs attention
	A32 pontoon repair – Sika product of epoxy mortar
	C pier corner brackets need re-galvanising – get 4 new ones & cycle through the pier
	Conduits under gangways need more support – P Pederson will advise
	A & B pier gangways are causing the piers to sag
	Stepping between pontoons on C, D & E piers

## 6 Matters Arising

6.1 Fairway Proposal

P Williams progressing this proposal.

6.2 Berth Licence Rules

Notice of the Consultation Meeting will be sent 12/7/2017 Winding up the Club – 80% of members at a meeting can wind up the Club?

6.3 Holding Tank Pump Out

P Pederson to alter - underway

6.4 Pile Guides

P McLea obtaining quotes – underway, additional quotes being sought

6.5 E Pier Flitch Plate

Quotes being sought – see above

6.6 Reclamation Title

Awaiting sign off – L Ayr will make enquiries

6.7 Haul Out Consent Variation

L Ayr will make enquiries as to the cost of applying for a consent variation.

#### 7 Correspondence

None

#### 8 Finances

A profit & loss report to 30 June 2017 & invoices for payment were distributed prior to the meeting.

Resolution	That the profit & loss report to 30 June 2017 be accepted & to authorise the
	invoices for payment as circulated prior & at the meeting to the meeting (\$13,000 to
	visitor pool account).
	Proposed P Stocker/Seconded P Williams: Carried

#### 9 Berth Licence Sales

Resolution	That it be recommended to the Kerikeri Cruising Club General Committee that the
	following licence transfer be ratified by the Club & the seal applied.
	B10 F Hunt to P Wilson, D Wilson & G Wilson
	Proposed P Harris/Seconded P Pederson: Carried

# 10 Compliance/Resource Consent

# 11 Manager's Report

End of year, annual fee invoicing, & visitor pool disbursements

#### 12 Policies

None this month. Berth Licence Rules being reviewed

#### 13 FMCA Committee

Consultation meeting 27th July

#### 14 General Committee Business

#### 15 General Business

Security Cameras - what costs - on next month's agenda

# 16 Next meeting

Tuesday 8 August 2017 Meeting closed 8.29pm

110717min.doc 3